

$$p(x) = x^{42} + x^{35} + x^{33} + x^{27} + x^{26} + x^{25} + x^{21} + x^{19} + x^{18} + x^{17} + x^{16} + x^{10} + x^{7} + x^{6} + x^{5} + x^{3} + x^{2} + x^{1} + 1$$

FIG. 2A




FIG. 2B






FIG. 3



.



200

FIG. 5




FIG. 6





FIG. 7A

705 E_F \otimes m_{n-2} 0 т г-3 0 \otimes m_{n-i+1} \otimes ج آ-0 \otimes m₂ $\widehat{\times}$ E T \odot و 0 ž Š

FIG. 7B

ر 715







FIG. 9








FIG. 11A




FIG. 11B




FIG. 12







FIG. 13






FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20

